

## STATE OF TEXAS WELL REPORT for Tracking #541714

Owner: <b>Phil Hagemeyer</b>	Owner Well #: <b>1</b>
Address: <b>1200 CR 65 Gatesville, TX 76528</b>	Grid #: <b>40-41-3</b>
Well Location: <b>1200 CR 65 Gatesville, TX 76528</b>	Latitude: <b>31° 22' 09" N</b>
Well County: <b>Coryell</b>	Longitude: <b>097° 53' 57" W</b>
	Elevation: <b>910 ft. above sea level</b>

Type of Work: <b>New Well</b>	Proposed Use: <b>Domestic</b>
-------------------------------	-------------------------------

Drilling Start Date: **3/26/2020**      Drilling End Date: **3/26/2020**

	Diameter (in.)	Top Depth (ft.)	Bottom Depth (ft.)
Borehole:	<b>8.75</b>	<b>0</b>	<b>20</b>
	<b>6.75</b>	<b>20</b>	<b>515</b>

Drilling Method: **Air Rotary**

Borehole Completion: **Straight Wall**

	Top Depth (ft.)	Bottom Depth (ft.)	Description (number of sacks & material)
Annular Seal Data:	<b>0</b>	<b>20</b>	<b>Cement 5 Bags/Sacks</b>

Seal Method: **Hand Mixed**

Sealed By: **Driller**

Distance to Property Line (ft.): **No Data**

Distance to Septic Field or other concentrated contamination (ft.): **No Data**

Distance to Septic Tank (ft.): **No Data**

Method of Verification: **No Data**

Surface Completion: <b>Surface Sleeve Installed</b>	<b>Surface Completion by Driller</b>
---	--------------------------------------

Water Level: **No Data**

Packers: **Rubber at 20 ft.  
Rubber at 380 ft.**

Type of Pump: **No Data**

Well Tests: **Jetted**      **Yield: 25 GPM after 1 hours, no drawdown specified**

Water Quality:	Strata Depth (ft.)	Water Type
	No Data	No Data

Chemical Analysis Made: **No**

Did the driller knowingly penetrate any strata which contained injurious constituents?: **No**

Certification Data: The driller certified that the driller drilled this well (or the well was drilled under the driller's direct supervision) and that each and all of the statements herein are true and correct. The driller understood that failure to complete the required items will result in the report(s) being returned for completion and resubmittal.

Company Information: **Lucy Creek Water Well Service**

**PO Box 1847  
Lampasas, TX 76550**

Driller Name: **Juan Munoz**

License Number: **54176**

Apprentice Name: **Mario Munoz**

Apprentice Number: **60427**

Comments: **TDS: 1200 PPM**

Lithology:  
DESCRIPTION & COLOR OF FORMATION MATERIAL

Top (ft.)	Bottom (ft.)	Description
0	10	Caliche
10	20	Yellow Overburden
20	120	Grey Shale
120	129	Puluxy Sand (Moist)
129	325	Grey Shale
325	341	Broken White Lime
341	350	Grey Shale
350	367	Brown Lime
367	395	Light Brown Shale
395	426	Dark Brown Clay
426	451	Fracture
451	476	Green Sandstone
476	484	Red / Brown Rock
484	488	Red and Green Lime
488	495	Frature / Yellow Lime
495	515	Red Rock / Fracture

Casing:  
BLANK PIPE & WELL SCREEN DATA

Dia (in.)	Type	Material	Sch./Gage	Top (ft.)	Bottom (ft.)
4.5	Blank	New Plastic (PVC)	SDR-17	0	380
4.5	Perforated or Slotted	New Plastic (PVC)	SDR-17 0.125	380	515

---

**IMPORTANT NOTICE FOR PERSONS HAVING WELLS DRILLED CONCERNING CONFIDENTIALITY**

TEX. OCC. CODE Title 12, Chapter 1901.251, authorizes the owner (owner or the person for whom the well was drilled) to keep information in Well Reports confidential. The Department shall hold the contents of the well log confidential and not a matter of public record if it receives, by certified mail, a written request to do so from the owner.

Please include the report's Tracking Number on your written request.

**Texas Department of Licensing and Regulation  
P.O. Box 12157  
Austin, TX 78711  
(512) 334-5540**